



June 13, 2013

Note: Updated 7/28/13 to correct the BIOS revision. The BIOS revision released with the 1.02 board was 6.5.101.

Product Advisory #1373 VL-EPM-24 (Tiger)

This is a formal notification regarding products supplied by VersaLogic Corp. Our records indicate that your company has purchased one or more of these products.

Please read this notice thoroughly to determine what impact this change may have on you in regards to your currently owned product or future purchases from VersaLogic Corp.

Affected Products

Products	Description	Old Revision Level	New Revision Level
VL-EPM-24EN, EU, SN, SU	Tiger SBCs	1.01	1.02

Background

The BIOS of the VL-EPM-24 was recently updated to revision 6.5.101 to resolve an issue with an occasional boot failure. This problem only occurred on the initial boot after the on-board battery (coin cell) was replaced.

Changes Made to Product

A minor change in the BIOS was made to implement an Intel-recommended fix. Using BIOS version 6.5.101 solves the problem.

Customer Impact

Fielded Units

The problem will occur only after a battery replacement, and only occurs once. Unless this causes a serious problem fielded units do not need to be updated.

Fielded units can be updated with BIOS revision 6.5.101 to avoid this problem. The BIOS can be downloaded from the [VL-EPM-24 support page](#).

Future Shipments

New revision boards will begin shipping in June of 2013.

Additional Information

For additional information or assistance related to this change, please contact VersaLogic Technical Support at Support@VersaLogic.com or call (503) 747-2261.