



Product Change Notification		Date September 11, 2020
Product	LR54/TX54/TX64	

Description of change	New firmware version 20.8.22.32 available for LR54/TX54/TX64 products. This is a major production release. Digi recommends all customers update their TX54/TX64 products to firmware v20.8.22.32
------------------------------	--

Reason for Change	New Firmware Version 20.8.22.32 provides: <ul style="list-style-type: none">• New Features• Enhancements• Bug Fixes• Security Fixes See Release Notes for more details.
--------------------------	--

Product Notice	<p>A new stable firmware version has been released for the Transportation cellular products, version 20.8.22.32. Use the link below to view the full list of changes, features, and fixes included in the new firmware.</p> <p>LR54/TX54/TX64 Release Notes</p> <p><u>To take advantage of the new features, you must take action to update your device.</u> Refer to the instructions to update your firmware in the release notes above for more information.</p> <p>Any questions or concerns about the new firmware, or for assistance upgrading your device(s), please contact the Digi Support team at tech.support@digi.com.</p>
-----------------------	---

Affected Part Numbers	TX54-A106, TX54-A112, TX54-A146, TX54-A206, TX54-A246 TX64-A121, TX64-A141, LR54-AA401, LR54-AW401
------------------------------	---

Timing of Change	Effective Immediately
-------------------------	-----------------------