

**Dear Customer,**

With this INFINEON Technologies Information Note we would like to inform you about the following

**Data Sheet update affecting products TLE9867QXW20 and TLE987xQXW40**

Infineon Technologies AG

Postal Address Headquarters: Am Campeon 1-12, D-85579 Neubiberg, Phone +49 (0)89 234-0

Chairman of the Supervisory Board: Wolfgang Mayrhuber

Management Board: Dr. Reinhard Ploss (CEO), Dominik Asam, Dr. Helmut Gassel, Jochen Hanebeck

Registered Office: Neubiberg Commercial Register

Amtsgericht München HRB 126492

N° 094/17

## Data Sheet update affecting products TLE9867QXW20, TLE987xQXW20/W40

► Products affected:	Sales Name	SP N°	OPN	Package
	TLE9867QXW20	SP001380954	TLE9867QXW20XUMA1	PG-VQFN-48
	TLE9873QXW40	SP001380956	TLE9873QXW40XUMA1	PG-VQFN-48
	TLE9877QXW40	SP001380958	TLE9877QXW40XUMA1	PG-VQFN-48
	TLE9879QXW40	SP001380960	TLE9879QXW40XUMA1	PG-VQFN-48

### ► Detailed Change Information:

**Subject:** Data Sheet update affecting products TLE9867QXW20 and TLE987xQXW40

**Reason:** Further parameter added for TLE9867QXW20 and TLE987xQXW40.

Description:	<u>Old</u>	<u>New</u>
<b>Data Sheet</b>	■ Rev. 1.0	■ Rev. 1.1

► **Product Identification:** Not applicable.

► **Impact of Change:** No change of product and process.  
No change in form, fit or function and reliability of the products affected.

► **Attachments:** 3\_cip17094: Data Sheet Rev. 1.1

► **Intended start of delivery:** Not applicable; documentation update only.

If you have any questions, please do not hesitate to contact your local Sales office.