



Phoenix Contact Inc.
 P.O. BOX 4100
 Harrisburg, PA 17111-0100
 Phone: 717-944-1300
 Fax: 717-944-1625

Product Discontinuation

PDN-IFC-5493-2020

| Business Unit | Product Line Code | Type of Change | Action | Date of Issue |
|-------------------------------------|-------------------|-------------------------|-------------------------------|---------------|
| IFC - Industrial Field Connectivity | BF7 | Product Discontinuation | Notify Distributors and Field | 5/15/2020 |

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

We aspire to always provide you with state-of-the-art products for your application. To this end, it is necessary for commercial and technical reasons to regularly check the product range and adjust the product life-cycle accordingly. For this reason, we are discontinuing some housings for our HEAVYCON connectors.

Alongside the HEAVYCON aluminum die cast connector housing with powder coating product range, we introduced the optimized series of HEAVYCON STA seawater-resistant aluminum die cast connector housings without powder coating to the market in 2015. Many functional advantages were included in the new HEAVYCON STA series:

- STA housings can be used for both shielded and unshielded applications with its conductive surface and seals.
- STA housings have a higher IP protection up to IP66/IP67 with optimized seals and locking latch.
- Customer specific threading options can be more quickly realized

Given these advantages of the HEAVYCON STA series, we hereby announce the discontinuation of the powder-coated housing series. To identify replacement parts, please see the attachments included for more details.

Stock Status

| | |
|-----------------------------------|-----|
| Can existing stock still be used? | Yes |
| Is mixture of stock acceptable? | No |

Transaction Dates

| | |
|---|------------|
| Last Buy from Phoenix Contact: | 12/31/2020 |
| Last Scheduled Ship from Phoenix Contact: | 4/30/2021 |



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Dean W Smith
dwsmith@phoenixcontact.com

Thank you,

Nathan Owens

Product Marketing Manager - IFC

Product Discontinuation

| Discontinued Part # | Type Description | Replacement Part # | Type Description |
|---------------------|------------------------|--------------------|------------------------------|
| 1460116 | HC-B 16-TFL-H-O1M32G | 1412689 | HC-STA-B16-HHFS-1TTM32-EL-AL |
| 1460117 | HC-B 16-TFL-H-O1M32S | 1412679 | HC-STA-B16-HHFS-1STM32-EL-AL |
| 1460118 | HC-B 16-TFL-H-O1PG21G | 1412702 | HC-STA-B16-HHFS-1TTP29-EL-AL |
| 1460119 | HC-B 16-TFL-H-O1PG21S | 1412683 | HC-STA-B16-HHFS-1STP21-EL-AL |
| 1460120 | HC-B 16-TFL-H-O1PG29G | 1412702 | HC-STA-B16-HHFS-1TTP29-EL-AL |
| 1460121 | HC-B 16-TFL-H-O1PG29S | 1412684 | HC-STA-B16-HHFS-1STP29-EL-AL |
| 1460122 | HC-B 16-TFL-H-O1STM25G | 1412729 | HC-STA-B16-HLFS-1TTM25-EL-AL |
| 1460123 | HC-B 16-TFL-H-O1STM25S | 1412725 | HC-STA-B16-HLFS-1STM25-EL-AL |
| 1460124 | HC-B 16-TFL-H-O1STM32G | 1412689 | HC-STA-B16-HHFS-1TTM32-EL-AL |
| 1460125 | HC-B 16-TFL-H-O1STM32S | 1412679 | HC-STA-B16-HHFS-1STM32-EL-AL |
| 1460126 | HC-B 16-TFL-H-O1STM40G | 1412700 | HC-STA-B16-HHFS-1TTM40-EL-AL |
| 1460127 | HC-B 16-TFL-H-O1STM40S | 1412682 | HC-STA-B16-HHFS-1STM40-EL-AL |
| 1460285 | HC-B 16-TFL-N-O1M25G | 1412729 | HC-STA-B16-HLFS-1TTM25-EL-AL |
| 1460320 | HC-B 16-TFL-N-O1M25S | 1412725 | HC-STA-B16-HLFS-1STM25-EL-AL |
| 1460101 | HC-B 16-TFL-N-O1PG21G | 1412732 | HC-STA-B16-HLFS-1TTP21-EL-AL |
| 1460103 | HC-B 16-TFL-N-O1PG21S | 1412728 | HC-STA-B16-HLFS-1STP21-EL-AL |
| 1460100 | HC-B 16-TFL-N-O1STM25G | 1412729 | HC-STA-B16-HLFS-1TTM25-EL-AL |
| 1460102 | HC-B 16-TFL-N-O1STM25S | 1412725 | HC-STA-B16-HLFS-1STM25-EL-AL |
| 1460095 | HC-B 16-TFL-N-O1STM32G | 1412730 | HC-STA-B16-HLFS-1TTM32-EL-AL |
| 1460109 | HC-B 16-TFL-N-O1STM32S | 1412726 | HC-STA-B16-HLFS-1STM32-EL-AL |
| 1771134 | HC-B 6-AML | 1411318 | HC-STA-B06-BWS-ELC-AL |
| 1409354 | HC-B 16-TFQ-H/O1STM32S | 1412649 | HC-STA-B16-HHFD-1STM32-EL-AL |
| 1460139 | HC-B 16-TFQ-H-M1PG21G | | |
| 1460140 | HC-B 16-TFQ-H-M1PG21S | | |
| 1460141 | HC-B 16-TFQ-H-M1PG29G | | |
| 1460142 | HC-B 16-TFQ-H-M1PG29S | | |
| 1460143 | HC-B 16-TFQ-H-O1M25S | 1412717 | HC-STA-B16-HLFD-1STM25-EL-AL |
| 1460144 | HC-B 16-TFQ-H-O1M32G | 1412653 | HC-STA-B16-HHFD-1TTM32-EL-AL |
| 1460145 | HC-B 16-TFQ-H-O1M32S | 1412649 | HC-STA-B16-HHFD-1STM32-EL-AL |
| 1460146 | HC-B 16-TFQ-H-O1PG21G | 1412669 | HC-STA-B16-HHFD-1TTP21-EL-AL |
| 1460147 | HC-B 16-TFQ-H-O1PG21S | 1412651 | HC-STA-B16-HHFD-1STP21-EL-AL |
| 1460148 | HC-B 16-TFQ-H-O1PG29G | 1412678 | HC-STA-B16-HHFD-1TTP29-EL-AL |
| 1460149 | HC-B 16-TFQ-H-O1PG29S | 1412652 | HC-STA-B16-HHFD-1STP29-EL-AL |
| 1460153 | HC-B 16-TFQ-H-O1STM25G | 1412721 | HC-STA-B16-HLFD-1TTM25-EL-AL |
| 1460154 | HC-B 16-TFQ-H-O1STM25S | 1412717 | HC-STA-B16-HLFD-1STM25-EL-AL |
| 1460155 | HC-B 16-TFQ-H-O1STM32G | 1412653 | HC-STA-B16-HHFD-1TTM32-EL-AL |
| 1460157 | HC-B 16-TFQ-H-O1STM40G | 1412654 | HC-STA-B16-HHFD-1TTM40-EL-AL |
| 1460158 | HC-B 16-TFQ-H-O1STM40S | 1412650 | HC-STA-B16-HHFD-1STM40-EL-AL |
| 1460044 | HC-B 16-TFQ-N-O1M25G | 1412721 | HC-STA-B16-HLFD-1TTM25-EL-AL |
| 1460135 | HC-B 16-TFQ-N-O1M25S | 1412717 | HC-STA-B16-HLFD-1STM25-EL-AL |
| 1460129 | HC-B 16-TFQ-N-O1PG21G | 1412724 | HC-STA-B16-HLFD-1TTP21-EL-AL |
| 1460131 | HC-B 16-TFQ-N-O1PG21S | 1412720 | HC-STA-B16-HLFD-1STP21-EL-AL |
| 1460128 | HC-B 16-TFQ-N-O1STM25G | 1412721 | HC-STA-B16-HLFD-1TTM25-EL-AL |
| 1460130 | HC-B 16-TFQ-N-O1STM25S | 1412717 | HC-STA-B16-HLFD-1STM25-EL-AL |
| 1460134 | HC-B 16-TFQ-N-O1STM32G | 1412722 | HC-STA-B16-HLFD-1TTM32-EL-AL |
| 1460160 | HC-B 16-TFQ-N-O1STM32S | 1412718 | HC-STA-B16-HLFD-1STM32-EL-AL |
| 1460170 | HC-B 16-TMQ-H-M1PG21G | | |
| 1460171 | HC-B 16-TMQ-H-M1PG21S | | |
| 1460173 | HC-B 16-TMQ-H-M1PG29G | | |
| 1460175 | HC-B 16-TMQ-H-M1PG29S | | |

Product Discontinuation

| | | | |
|---------|------------------------|---------|--------------------------------|
| 1460177 | HC-B 16-TMQ-H-O1M32G | 1412708 | HC-STA-B16-HHWD-1TTM32-EL-AL |
| 1460178 | HC-B 16-TMQ-H-O1M32S | 1412703 | HC-STA-B16-HHWD-1STM32-EL-AL |
| 1460182 | HC-B 16-TMQ-H-O1STM25S | 1412733 | HC-STA-B16-HLWD-1STM25-EL-AL |
| 1460184 | HC-B 16-TMQ-H-O1STM32S | 1412703 | HC-STA-B16-HHWD-1STM32-EL-AL |
| 1460162 | HC-B 16-TMQ-N-O1M25G | 1412738 | HC-STA-B16-HLWD-1TTM25-EL-AL |
| 1460163 | HC-B 16-TMQ-N-O1M25S | 1412733 | HC-STA-B16-HLWD-1STM25-EL-AL |
| 1460164 | HC-B 16-TMQ-N-O1PG21G | 1412741 | HC-STA-B16-HLWD-1TTP21-EL-AL |
| 1771956 | HC-B 24-AFQD | 1411332 | HC-STA-B24-BFDC-ELC-AL |
| 1771930 | HC-B 24-AML | 1411329 | HC-STA-B24-BWS-ELC-AL |
| 1771943 | HC-B 24-AMLD | 1411330 | HC-STA-B24-BWSC-ELC-AL |
| 1771927 | HC-B 24-AMQ | 1411331 | HC-STA-B24-BWD-ELC-AL |
| 1460317 | HC-B 24-KML-H-M1PG21 | | |
| 1460324 | HC-B 24-KML-H-O1STM25 | | |
| 1460325 | HC-B 24-KML-H-O1STM32 | 1412746 | HC-STA-B24-CHWS-1TTM32-ELC-AL |
| 1460326 | HC-B 24-KML-H-O1STM40 | 1412747 | HC-STA-B24-CHWS-1TTM40-ELC-AL |
| 1460327 | HC-B 24-KMQ-H-M1PG21 | | |
| 1460328 | HC-B 24-KMQ-H-M1PG29 | | |
| 1460330 | HC-B 24-KMQ-H-O1PG29 | 1412745 | HC-STA-B24-CHWD-1TTP29-ELC-AL |
| 1460335 | HC-B 24-KMQ-H-O1STM32 | 1412742 | HC-STA-B24-CHWD-1TTM32-ELC-AL |
| 1460336 | HC-B 24-KMQ-H-O1STM40 | 1412743 | HC-STA-B24-CHWD-1TTM40-ELC-AL |
| 1584677 | HC-B 24-LB | 1412885 | HC-STA-B24-SL-PLBK |
| 1772010 | HC-B 24-SFQD-67/M1PG21 | | |
| 1772023 | HC-B 24-SFQD-67/M2PG21 | | |
| 1604830 | HC-B 24-SFQD-67/O1M25 | 1412869 | HC-STA-B24-SLFDC-2SSM25-ELC-AL |
| 1674118 | HC-B 24-SFQD-67/O1PG21 | 1412871 | HC-STA-B24-SLFDC-2SSP21-ELC-AL |
| 1604831 | HC-B 24-SFQD-67/O2M25 | 1412869 | HC-STA-B24-SLFDC-2SSM25-ELC-AL |
| 1674121 | HC-B 24-SFQD-67/O2PG21 | 1412871 | HC-STA-B24-SLFDC-2SSP21-ELC-AL |
| 1645736 | HC-B 24-SFQD-84/O1M32 | 1412870 | HC-STA-B24-SLFDC-2SSM32-ELC-AL |
| 1586934 | HC-B 24-SML-67/M1M25 | | |
| 1771985 | HC-B 24-SML-67/M1PG21 | | |
| 1771998 | HC-B 24-SML-67/M2PG21 | | |
| 1674134 | HC-B 24-SML-67/O1PG21 | 1412879 | HC-STA-B24-SLWS-2SSP21-ELC-AL |
| 1646337 | HC-B 24-SML-68/O1M25 | 1412877 | HC-STA-B24-SLWS-2SSM25-ELC-AL |
| 1646340 | HC-B 24-SML-68/O2M25 | 1412877 | HC-STA-B24-SLWS-2SSM25-ELC-AL |
| 1645752 | HC-B 24-SML-84/O1M32 | 1082592 | HC-STA-B24-SHWS-2SSM32-ELC-AL |
| 1645765 | HC-B 24-SML-84/O1M40 | 1082593 | HC-STA-B24-SHWS-2SSM40-ELC-AL |
| 1677979 | HC-B 24-SML-84/O1PG29 | 1082593 | HC-STA-B24-SHWS-2SSM40-ELC-AL |

Product Discontinuation

| | | | |
|---------|------------------------|---------|--------------------------------|
| 1604832 | HC-B 24-SML-84/O2M32 | 1082592 | HC-STA-B24-SHWS-2SSM32-ELC-AL |
| 1586950 | HC-B 24-SMLD-67/M1M25 | | |
| 1772036 | HC-B 24-SMLD-67/M1PG21 | | |
| 1772049 | HC-B 24-SMLD-67/M2PG21 | | |
| 1604833 | HC-B 24-SMLD-67/O1M25 | 1412881 | HC-STA-B24-SLWSC-2SSM25-ELC-AL |
| 1674150 | HC-B 24-SMLD-67/O1PG21 | 1412883 | HC-STA-B24-SLWSC-2SSP21-ELC-AL |
| 1604834 | HC-B 24-SMLD-67/O2M25 | 1412881 | HC-STA-B24-SLWSC-2SSM25-ELC-AL |
| 1674163 | HC-B 24-SMLD-67/O2PG21 | 1412883 | HC-STA-B24-SLWSC-2SSP21-ELC-AL |
| 1678004 | HC-B 24-SMLD-84/O1PG21 | 1082596 | HC-STA-B24-SHWSC-2SSM32-ELC-AL |
| 1678017 | HC-B 24-SMLD-84/O1PG29 | 1082597 | HC-STA-B24-SHWSC-2SSM40-ELC-AL |
| 1645794 | HC-B 24-SMLD-84/O2M32 | 1082596 | HC-STA-B24-SHWSC-2SSM32-ELC-AL |
| 1645817 | HC-B 24-SMLD-84/O2M40 | 1082597 | HC-STA-B24-SHWSC-2SSM40-ELC-AL |
| 1678033 | HC-B 24-SMLD-84/O2PG29 | 1082597 | HC-STA-B24-SHWSC-2SSM40-ELC-AL |
| 1586976 | HC-B 24-SMQ-67/M1M25 | | |
| 1771969 | HC-B 24-SMQ-67/M1PG21 | | |
| 1771972 | HC-B 24-SMQ-67/M2PG21 | | |
| 1604835 | HC-B 24-SMQ-67/O1M25 | 1412873 | HC-STA-B24-SLWD-2SSM25-ELC-AL |
| 1674176 | HC-B 24-SMQ-67/O1PG21 | 1412875 | HC-STA-B24-SLWD-2SSP21-ELC-AL |
| 1646353 | HC-B 24-SMQ-68/O2M25 | 1412873 | HC-STA-B24-SLWD-2SSM25-ELC-AL |
| 1604836 | HC-B 24-SMQ-84/O1M32 | 1082604 | HC-STA-B24-SHWD-2SSM32-ELC-AL |
| 1645419 | HC-B 24-SMQ-84/O1M40 | 1082605 | HC-STA-B24-SHWD-2SSM40-ELC-AL |
| 1678046 | HC-B 24-SMQ-84/O1PG21 | 1082604 | HC-STA-B24-SHWD-2SSM32-ELC-AL |
| 1678402 | HC-B 24-SMQ-84/O1PG29 | 1082605 | HC-STA-B24-SHWD-2SSM40-ELC-AL |
| 1604837 | HC-B 24-SMQ-84/O2M32 | 1082604 | HC-STA-B24-SHWD-2SSM32-ELC-AL |
| 1645723 | HC-B 24-SMQ-84/O2M40 | 1082605 | HC-STA-B24-SHWD-2SSM40-ELC-AL |
| 1678431 | HC-B 24-SMQ-84/O2PG29 | 1082605 | HC-STA-B24-SHWD-2SSM40-ELC-AL |
| 1460199 | HC-B 24-TFL-H-M1PG21G | | |
| 1460200 | HC-B 24-TFL-H-M1PG21S | | |
| 1460201 | HC-B 24-TFL-H-M1PG29G | | |
| 1460202 | HC-B 24-TFL-H-M1PG29S | | |
| 1460203 | HC-B 24-TFL-H-O1M25G | 1412788 | HC-STA-B24-HLFS-1TTM25-EL-AL |
| 1460204 | HC-B 24-TFL-H-O1M32G | 1412761 | HC-STA-B24-HHFS-1TTM32-EL-AL |
| 1460205 | HC-B 24-TFL-H-O1M32S | 1412757 | HC-STA-B24-HHFS-1STM32-EL-AL |
| 1460206 | HC-B 24-TFL-H-O1PG21S | 1412759 | HC-STA-B24-HHFS-1STP21-EL-AL |

Product Discontinuation

| | | | |
|---------|------------------------|---------|------------------------------|
| 1460207 | HC-B 24-TFL-H-O1PG29G | 1412763 | HC-STA-B24-HHFS-1TTP29-EL-AL |
| 1460208 | HC-B 24-TFL-H-O1PG29S | 1412760 | HC-STA-B24-HHFS-1STP29-EL-AL |
| 1460210 | HC-B 24-TFL-H-O1STM25G | 1412788 | HC-STA-B24-HLFS-1TTM25-EL-AL |
| 1460211 | HC-B 24-TFL-H-O1STM25S | 1412783 | HC-STA-B24-HLFS-1STM25-EL-AL |
| 1460212 | HC-B 24-TFL-H-O1STM32G | 1412761 | HC-STA-B24-HHFS-1TTM32-EL-AL |
| 1460213 | HC-B 24-TFL-H-O1STM32S | 1412757 | HC-STA-B24-HHFS-1STM32-EL-AL |
| 1460214 | HC-B 24-TFL-H-O1STM40G | 1412098 | HC-STA-B24-HHFS-1TTM40-EL-AL |
| 1460215 | HC-B 24-TFL-H-O1STM40S | 1412758 | HC-STA-B24-HHFS-1STM40-EL-AL |
| 1460064 | HC-B 24-TFL-N-O1M25G | 1412788 | HC-STA-B24-HLFS-1TTM25-EL-AL |
| 1460333 | HC-B 24-TFL-N-O1M25S | 1412783 | HC-STA-B24-HLFS-1STM25-EL-AL |
| 1460085 | HC-B 24-TFL-N-O1M32S | 1412784 | HC-STA-B24-HLFS-1STM32-EL-AL |
| 1460190 | HC-B 24-TFL-N-O1PG21G | 1412791 | HC-STA-B24-HLFS-1TTP21-EL-AL |
| 1460193 | HC-B 24-TFL-N-O1PG21S | 1412786 | HC-STA-B24-HLFS-1STP21-EL-AL |
| 1460293 | HC-B 24-TFL-N-O1PG29G | 1412792 | HC-STA-B24-HLFS-1TTP29-EL-AL |
| 1460194 | HC-B 24-TFL-N-O1PG29S | 1412760 | HC-STA-B24-HHFS-1STP29-EL-AL |
| 1460189 | HC-B 24-TFL-N-O1STM25G | 1412788 | HC-STA-B24-HLFS-1TTM25-EL-AL |
| 1460191 | HC-B 24-TFL-N-O1STM25S | 1412783 | HC-STA-B24-HLFS-1STM25-EL-AL |
| 1460297 | HC-B 24-TFL-N-O1STM32G | 1412789 | HC-STA-B24-HLFS-1TTM32-EL-AL |
| 1460192 | HC-B 24-TFL-N-O1STM32S | 1412784 | HC-STA-B24-HLFS-1STM32-EL-AL |
| 1460230 | HC-B 24-TFQ-H-M1PG21G | | |
| 1460231 | HC-B 24-TFQ-H-M1PG21S | | |
| 1460232 | HC-B 24-TFQ-H-M1PG29G | | |
| 1460233 | HC-B 24-TFQ-H-M1PG29S | | |
| 1460234 | HC-B 24-TFQ-H-O1M25G | 1412778 | HC-STA-B24-HLFD-1TTM25-EL-AL |
| 1460235 | HC-B 24-TFQ-H-O1M25S | 1412773 | HC-STA-B24-HLFD-1STM25-EL-AL |
| 1460236 | HC-B 24-TFQ-H-O1M32G | 1412754 | HC-STA-B24-HHFD-1TTM32-EL-AL |
| 1460237 | HC-B 24-TFQ-H-O1M32S | 1412750 | HC-STA-B24-HHFD-1STM32-EL-AL |
| 1460350 | HC-B 24-TFQ-H-O1PG21G | 1412755 | HC-STA-B24-HHFD-1TTP21-EL-AL |
| 1460238 | HC-B 24-TFQ-H-O1PG21S | 1412752 | HC-STA-B24-HHFD-1STP21-EL-AL |
| 1460239 | HC-B 24-TFQ-H-O1PG29G | 1412756 | HC-STA-B24-HHFD-1TTP29-EL-AL |
| 1460240 | HC-B 24-TFQ-H-O1PG29S | 1412753 | HC-STA-B24-HHFD-1STP29-EL-AL |
| 1460241 | HC-B 24-TFQ-H-O1STM25G | 1412778 | HC-STA-B24-HLFD-1TTM25-EL-AL |
| 1460242 | HC-B 24-TFQ-H-O1STM25S | 1412773 | HC-STA-B24-HLFD-1STM25-EL-AL |
| 1460243 | HC-B 24-TFQ-H-O1STM32G | 1412754 | HC-STA-B24-HHFD-1TTM32-EL-AL |
| 1409367 | HC-B 24-TFQ-H-O1STM32S | 1412750 | HC-STA-B24-HHFD-1STM32-EL-AL |
| 1460245 | HC-B 24-TFQ-H-O1STM40G | 1412099 | HC-STA-B24-HHFD-1TTM40-EL-AL |
| 1460246 | HC-B 24-TFQ-H-O1STM40S | 1412751 | HC-STA-B24-HHFD-1STM40-EL-AL |
| 1460221 | HC-B 24-TFQ-N-M1PG21S | | |
| 1460031 | HC-B 24-TFQ-N-O1M25G | 1412778 | HC-STA-B24-HLFD-1TTM25-EL-AL |
| 1460265 | HC-B 24-TFQ-N-O1M25S | 1412773 | HC-STA-B24-HLFD-1STM25-EL-AL |
| 1460165 | HC-B 24-TFQ-N-O1M32S | 1412774 | HC-STA-B24-HLFD-1STM32-EL-AL |
| 1460220 | HC-B 24-TFQ-N-O1PG21G | 1412781 | HC-STA-B24-HLFD-1TTP21-EL-AL |
| 1460224 | HC-B 24-TFQ-N-O1PG21S | 1412776 | HC-STA-B24-HLFD-1STP21-EL-AL |
| 1460332 | HC-B 24-TFQ-N-O1PG29G | 1412782 | HC-STA-B24-HLFD-1TTP29-EL-AL |
| 1460218 | HC-B 24-TFQ-N-O1STM25G | 1412778 | HC-STA-B24-HLFD-1TTM25-EL-AL |
| 1460219 | HC-B 24-TFQ-N-O1STM25S | 1412773 | HC-STA-B24-HLFD-1STM25-EL-AL |
| 1460222 | HC-B 24-TFQ-N-O1STM32G | 1412779 | HC-STA-B24-HLFD-1TTM32-EL-AL |
| 1460223 | HC-B 24-TFQ-N-O1STM32S | 1412774 | HC-STA-B24-HLFD-1STM32-EL-AL |
| 1460255 | HC-B 24-TMQ-H-M1PG21G | | |
| 1460256 | HC-B 24-TMQ-H-M1PG21S | | |
| 1460257 | HC-B 24-TMQ-H-M1PG29G | | |



Product Discontinuation

| | | | |
|---------|-------------------------|---------|-------------------------------|
| 1460259 | HC-B 24-TMQ-H-M1PG29S | | |
| 1460261 | HC-B 24-TMQ-H-O1M25G | 1412799 | HC-STA-B24-HLWD-1TTM25-EL-AL |
| 1460262 | HC-B 24-TMQ-H-O1M25S | 1412793 | HC-STA-B24-HLWD-1STM25-EL-AL |
| 1460186 | HC-B 24-TMQ-H-O1PG29S | 1412768 | HC-STA-B24-HHWD-1STP29-EL-AL |
| 1460269 | HC-B 24-TMQ-H-O1STM32G | 1412769 | HC-STA-B24-HHWD-1TTM32-EL-AL |
| 1460270 | HC-B 24-TMQ-H-O1STM32S | 1412764 | HC-STA-B24-HHWD-1STM32-EL-AL |
| 1460271 | HC-B 24-TMQ-H-O1STM40G | 1412770 | HC-STA-B24-HHWD-1TTM40-EL-AL |
| 1460272 | HC-B 24-TMQ-H-O1STM40S | 1412766 | HC-STA-B24-HHWD-1STM40-EL-AL |
| 1775693 | HC-B 32-AMQ | 1424845 | HC-STA-B32-BWD-ELC-AL |
| 1775732 | HC-B 32-KMQ-82/M1PG29 | | |
| 1604863 | HC-B 32-KMQ-82/O1M25 | | |
| 1675023 | HC-B 32-KMQ-82/O1PG29 | 1424839 | HC-STA-B32-CHWD-1TTP29-ELC-AL |
| 1647284 | HC-B 32-KMQ-82/O1STM32 | 1424842 | HC-STA-B32-CHWD-1TTM32-ELC-AL |
| 1647297 | HC-B 32-KMQ-82/O1STM40 | 1424843 | HC-STA-B32-CHWD-1TTM40-ELC-AL |
| 1775703 | HC-B 32-SMQ-72/M1PG29 | | |
| 1775716 | HC-B 32-SMQ-72/M2PG29 | 1424846 | HC-STA-B32-SHWD-2SSP29-ELC-AL |
| 1604867 | HC-B 32-SMQ-72/O1M32 | 1424848 | HC-STA-B32-SHWD-2SSM32-ELC-AL |
| 1675036 | HC-B 32-SMQ-72/O1PG29 | 1424846 | HC-STA-B32-SHWD-2SSP29-ELC-AL |
| 1604868 | HC-B 32-SMQ-72/O2M32 | 1424848 | HC-STA-B32-SHWD-2SSM32-ELC-AL |
| 1604869 | HC-B 32-SMQ-72/O2M40 | 1424849 | HC-STA-B32-SHWD-2SSM40-ELC-AL |
| 1675049 | HC-B 32-SMQ-72/O2PG29 | 1424846 | HC-STA-B32-SHWD-2SSP29-ELC-AL |
| 1775677 | HC-B 32-TFQ-80/M1PG21G | | |
| 1775651 | HC-B 32-TFQ-80/M1PG21S | | |
| 1775680 | HC-B 32-TFQ-80/M1PG29G | | |
| 1775664 | HC-B 32-TFQ-80/M1PG29S | | |
| 1604870 | HC-B 32-TFQ-80/O1M25G | | |
| 1604871 | HC-B 32-TFQ-80/O1M25S | | |
| 1604872 | HC-B 32-TFQ-80/O1M32S | 1424836 | HC-STA-B32-HHFD-1STM32-EL-AL |
| 1675081 | HC-B 32-TFQ-80/O1PG29G | 1424827 | HC-STA-B32-HHFD-1TTP29-EL-AL |
| 1675094 | HC-B 32-TFQ-80/O1PG29S | 1424833 | HC-STA-B32-HHFD-1STP29-EL-AL |
| 1645134 | HC-B 32-TFQ-80/O1STM25G | | |
| 1645147 | HC-B 32-TFQ-80/O1STM25S | | |
| 1645383 | HC-B 32-TFQ-80/O1STM32G | 1424830 | HC-STA-B32-HHFD-1TTM32-EL-AL |
| 1645150 | HC-B 32-TFQ-80/O1STM32S | 1424836 | HC-STA-B32-HHFD-1STM32-EL-AL |
| 1647307 | HC-B 32-TFQ-80/O1STM40G | 1424831 | HC-STA-B32-HHFD-1TTM40-EL-AL |
| 1645451 | HC-B 32-TFQ-80/O1STM40S | 1424837 | HC-STA-B32-HHFD-1STM40-EL-AL |
| 1460197 | HC-B 32-TFQ-80/O1STM50G | 1424832 | HC-STA-B32-HHFD-1TTM50-EL-AL |
| 1772175 | HC-B 48-AML | 1424863 | HC-STA-B48-BWS-EMC-AL |
| 1772188 | HC-B 48-AML | 1424864 | HC-STA-B48-BWSC-EMC-AL |
| 1772191 | HC-B 48-SML-100/M1PG29 | | |
| 1772201 | HC-B 48-SML-100/M2PG29 | | |
| 1604875 | HC-B 48-SML-100/O1M32 | 1424867 | HC-STA-B48-SHWS-2SSM32-EMC-AL |

Product Discontinuation

| | | | |
|---------|-------------------------|---------|------------------------------------|
| 1675117 | HC-B 48-SML-100/O1PG29 | 1424865 | HC-STA-B48-SHWS-2SSP29-EMC-A L |
| 1604876 | HC-B 48-SML-100/O2M40 | 1424868 | HC-STA-B48-SHWS-2SSM40-EMC-A L |
| 1675120 | HC-B 48-SML-100/O2PG29 | 1424865 | HC-STA-B48-SHWS-2SSP29-EMC-A L |
| 1772214 | HC-B 48-SMLD-100/M1PG29 | | |
| 1772227 | HC-B 48-SMLD-100/M2PG29 | | |
| 1604877 | HC-B 48-SMLD-100/O1M32 | 1424873 | HC-STA-B48-SHWSC-2SSM32-EMC -AL |
| 1604878 | HC-B 48-SMLD-100/O2M40 | 1424874 | HC-STA-B48-SHWSC-2SSM40-EMC -AL |
| 1772159 | HC-B 48-TFL-96/M1PG29G | | |
| 1772133 | HC-B 48-TFL-96/M1PG29S | | |
| 1772162 | HC-B 48-TFL-96/M1PG36G | | |
| 1772146 | HC-B 48-TFL-96/M1PG36S | | |
| 1604879 | HC-B 48-TFL-96/O1M40G | 1424855 | HC-STA-B48-HHFS-1TTM40-EM-AL |
| 1604880 | HC-B 48-TFL-96/O1M40S | 1424861 | HC-STA-B48-HHFS-1STM40-EM-AL |
| 1675159 | HC-B 48-TFL-96/O1PG29G | 1424851 | HC-STA-B48-HHFS-1TTP29-EM-AL |
| 1675162 | HC-B 48-TFL-96/O1PG29S | 1424857 | HC-STA-B48-HHFS-1STP29-EM-AL |
| 1675175 | HC-B 48-TFL-96/O1PG36G | 1424852 | HC-STA-B48-HHFS-1TTP36-EM-AL |
| 1675188 | HC-B 48-TFL-96/O1PG36S | 1424858 | HC-STA-B48-HHFS-1STP36-EM-AL |
| 1647349 | HC-B 48-TFL-96/O1STM32G | 1424854 | HC-STA-B48-HHFS-1TTM32-EM-AL |
| 1647336 | HC-B 48-TFL-96/O1STM32S | 1424860 | HC-STA-B48-HHFS-1STM32-EM-AL |
| 1647310 | HC-B 48-TFL-96/O1STM40G | 1424855 | HC-STA-B48-HHFS-1TTM40-EM-AL |
| 1647323 | HC-B 48-TFL-96/O1STM40S | 1424861 | HC-STA-B48-HHFS-1STM40-EM-AL |
| 1460337 | HC-B 48-TFL-96/O1STM50G | 1424856 | HC-STA-B48-HHFS-1TTM50-EM-AL |
| 1460351 | HC-B 48-TFL-96/O1STM50S | 1424862 | HC-STA-B48-HHFS-1STM50-EM-AL |
| 1773035 | HC-D 7-AML-24/GR | 1419249 | HC-STA-D07-BWS-EL-AL |
| 1604891 | HC-D 7-TFL-48/O1M20S | 1419235 | HC-STA-D07-HHFS-1STM20-EL-AL |
| 1679582 | HC-D 15-FL-DI | | |
| 1661189 | HC-D 15-PR-DI | | |
| 1679595 | HC-D 25-FL-DI | | |
| 1408054 | HC-D 25-PR-DI | | |
| 1663019 | HC-B 6-FL-DI | | |
| 1411436 | HC-B 6-FL-DI-N | | |
| 1663022 | HC-B 6-PR-DI | | |
| 1662146 | HC-B 10-FL-DI | | |
| 1411449 | HC-B 10-FL-DI-N | | |
| 1663035 | HC-B 10-PR-DI | | |
| 1661451 | HC-B 16-FL-DI | | |
| 1411452 | HC-B 16-FL-DI-N | | |
| 1661079 | HC-B 16-PR-DI | | |
| 1774665 | HC-B 24-FL-DI | | |
| 1771147 | HC-B 6-AMLD | 1411319 | HC-STA-B06-BWSC-ELC-AL |
| 1771150 | HC-B 6-SML-52/M1PG16 | | |
| 1771163 | HC-B 6-SML-52/M2PG16 | | |
| 1604721 | HC-B 6-SML-52/O1M20 | 1412821 | HC-STA-B06-SLWS-2SSM20-ELC-A L |
| 1604722 | HC-B 6-SML-52/O1M25 | 1412822 | HC-STA-B06-SLWS-2SSM25-ELC-A L |
| 1675214 | HC-B 6-SML-52/O1PG16 | 1412823 | HC-STA-B06-SLWS-2SSP16-ELC-AL |



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

| | | | |
|---------|------------------------|---------|--------------------------------|
| 1604723 | HC-B 6-SML-52/O2M20 | 1412821 | HC-STA-B06-SLWS-2SSM20-ELC-AL |
| 1604724 | HC-B 6-SML-52/O2M25 | 1412822 | HC-STA-B06-SLWS-2SSM25-ELC-AL |
| 1675230 | HC-B 6-SML-52/O2PG16 | 1412823 | HC-STA-B06-SLWS-2SSP16-ELC-AL |
| 1604725 | HC-B 6-SML-74/O1M25 | 1082556 | HC-STA-B06-SHWS-2SSM25-ELC-AL |
| 1646845 | HC-B 6-SML-74/O1M32 | 1082559 | HC-STA-B06-SHWS-2SSM32-ELC-AL |
| 1678114 | HC-B 6-SML-74/O1PG21 | 1082559 | HC-STA-B06-SHWS-2SSM32-ELC-AL |
| 1411465 | HC-B 24-FL-DI-N | | |
| 1663048 | HC-B 24-PR-DI | | |
| 1774678 | HC-B 48-FL-DI | | |
| 1636114 | HC-B 48-LB ERSBOLZ | | |
| 1663051 | HC-B 48-PR-DI | | |
| 1408070 | HC-B/D-ERSLABO-SD-KU | | |
| 1646858 | HC-B 6-SML-74/O2M32 | 1082559 | HC-STA-B06-SHWS-2SSM32-ELC-AL |
| 1678130 | HC-B 6-SML-74/O2PG21 | 1082559 | HC-STA-B06-SHWS-2SSM32-ELC-AL |
| 1586756 | HC-B 6-SMLD-52/M1M20 | | |
| 1771176 | HC-B 6-SMLD-52/M1PG16 | | |
| 1771189 | HC-B 6-SMLD-52/M2PG16 | | |
| 1604728 | HC-B 6-SMLD-52/O1M25 | 1412826 | HC-STA-B06-SLWSC-2SSM25-ELC-AL |
| 1675269 | HC-B 6-SMLD-52/O1PG16 | 1412827 | HC-STA-B06-SLWSC-2SSP16-ELC-AL |
| 1604729 | HC-B 6-SMLD-52/O2M20 | 1412825 | HC-STA-B06-SLWSC-2SSM20-ELC-AL |
| 1604730 | HC-B 6-SMLD-52/O2M25 | 1412826 | HC-STA-B06-SLWSC-2SSM25-ELC-AL |
| 1675272 | HC-B 6-SMLD-52/O2PG16 | 1412827 | HC-STA-B06-SLWSC-2SSP16-ELC-AL |
| 1678156 | HC-B 6-SMLD-74/O1PG21 | 1082576 | HC-STA-B06-SHWSC-2SSM32-ELC-AL |
| 1678169 | HC-B 6-SMLD-74/O1PG29 | 1082577 | HC-STA-B06-SHWSC-2SSM40-ELC-AL |
| 1646861 | HC-B 6-SMLD-74/O2M32 | 1082576 | HC-STA-B06-SHWSC-2SSM32-ELC-AL |
| 1678185 | HC-B 6-SMLD-74/O2PG29 | 1082577 | HC-STA-B06-SHWSC-2SSM40-ELC-AL |
| 1460319 | HC-B 6-TFL-N-O1M20G | 1412574 | HC-STA-B06-HLFS-1TTM20-EL-AL |
| 1460227 | HC-B 6-TFL-N-O1M20S | 1412570 | HC-STA-B06-HLFS-1STM20-EL-AL |
| 1460196 | HC-B 6-TFL-N-O1M25S | 1412571 | HC-STA-B06-HLFS-1STM25-EL-AL |
| 1460277 | HC-B 06-KML-H-M1PG13.5 | | |
| 1460278 | HC-B 06-KML-H-O1M20 | 1412555 | HC-STA-B06-CHWS-1TTM20-ELC-AL |
| 1460282 | HC-B 06-KML-H-O1STM20 | 1412555 | HC-STA-B06-CHWS-1TTM20-ELC-AL |
| 1460275 | HC-B 06-SMLD-52/O1M20 | 1412825 | HC-STA-B06-SLWSC-2SSM20-ELC-AL |
| 1460352 | HC-B 06-TFL-H-M1PG21S | | |

Product Discontinuation

| | | | |
|---------|-------------------------|---------|-------------------------------|
| 1460353 | HC-B 06-TFL-H-O1M20S | 1412570 | HC-STA-B06-HLFS-1STM20-EL-AL |
| 1460354 | HC-B 06-TFL-H-O1M25G | 1412566 | HC-STA-B06-HHFS-1TTM25-EL-AL |
| 1460019 | HC-B 06-TFL-H-O1M25S | 1412562 | HC-STA-B06-HHFS-1STM25-EL-AL |
| 1460020 | HC-B 06-TFL-H-O1M32S | 1412563 | HC-STA-B06-HHFS-1STM32-EL-AL |
| 1460025 | HC-B 06-TFL-H-O1STM20G | 1412574 | HC-STA-B06-HLFS-1TTM20-EL-AL |
| 1460026 | HC-B 06-TFL-H-O1STM20S | 1412570 | HC-STA-B06-HLFS-1STM20-EL-AL |
| 1460343 | HC-B 06-TFL-N-M1M20S | | |
| 1460338 | HC-B 06-TFL-N-M1PG13.5G | | |
| 1460338 | HC-B 06-TFL-N-M1PG13.5G | | |
| 1460280 | HC-B 6-KML-H-O1PG21 | 1412559 | HC-STA-B06-CHWS-1TTP21-ELC-AL |
| 1460283 | HC-B 6-KML-H-O1STM25 | 1412556 | HC-STA-B06-CHWS-1TTM25-ELC-AL |
| 1460284 | HC-B 6-KML-H-O1STM32 | 1412557 | HC-STA-B06-CHWS-1TTM32-ELC-AL |
| 1460137 | HC-B 6-KML-N-O1STM20 | 1412555 | HC-STA-B06-CHWS-1TTM20-ELC-AL |
| 1584211 | HC-B 6-LB | 1412591 | HC-STA-B06-SL-PLBK |
| 1460021 | HC-B 6-TFL-H-O1PG21G | 1412568 | HC-STA-B06-HHFS-1TTP21-EL-AL |
| 1460022 | HC-B 6-TFL-H-O1PG21S | 1412564 | HC-STA-B06-HHFS-1STP21-EL-AL |
| 1460023 | HC-B 6-TFL-H-O1PG29G | 1412569 | HC-STA-B06-HHFS-1TTP29-EL-AL |
| 1460024 | HC-B 6-TFL-H-O1PG29S | 1412565 | HC-STA-B06-HHFS-1STP29-EL-AL |
| 1460027 | HC-B 6-TFL-H-O1STM25G | 1412566 | HC-STA-B06-HHFS-1TTM25-EL-AL |
| 1460028 | HC-B 6-TFL-H-O1STM25S | 1412562 | HC-STA-B06-HHFS-1STM25-EL-AL |
| 1460029 | HC-B 6-TFL-H-O1STM32G | 1412567 | HC-STA-B06-HHFS-1TTM32-EL-AL |
| 1460030 | HC-B 6-TFL-H-O1STM32S | 1412563 | HC-STA-B06-HHFS-1STM32-EL-AL |
| 1460340 | HC-B 6-TFL-N-O1PG13.5G | 1412576 | HC-STA-B06-HLFS-1TTP13-EL-AL |
| 1460348 | HC-B 6-TFL-N-O1PG13.5S | 1412572 | HC-STA-B06-HLFS-1STP13-EL-AL |
| 1460341 | HC-B 6-TFL-N-O1PG16G | 1412577 | HC-STA-B06-HLFS-1TTP16-EL-AL |
| 1460349 | HC-B 6-TFL-N-O1PG16S | 1412573 | HC-STA-B06-HLFS-1STP16-EL-AL |
| 1460339 | HC-B 6-TFL-N-O1STM20G | 1412574 | HC-STA-B06-HLFS-1TTM20-EL-AL |
| 1460346 | HC-B 6-TFL-N-O1STM20S | 1412570 | HC-STA-B06-HLFS-1STM20-EL-AL |
| 1460258 | HC-B 6-TFL-N-O1STM25G | 1412575 | HC-STA-B06-HLFS-1TTM25-EL-AL |
| 1460347 | HC-B 6-TFL-N-O1STM25S | 1412571 | HC-STA-B06-HLFS-1STM25-EL-AL |
| 1637265 | HC-B 10-24-QB | 1412886 | HC-STA-B10-24-DL-PLBK |
| 1771341 | HC-B 10-AFQD | 1411323 | HC-STA-B10-BFDC-ELC-AL |
| 1771338 | HC-B 10-AML | 1411320 | HC-STA-B10-BWS-ELC-AL |
| 1771354 | HC-B 10-AMLD | 1411321 | HC-STA-B10-BWSC-ELC-AL |
| 1771325 | HC-B 10-AMQ | 1411322 | HC-STA-B10-BWD-ELC-AL |
| 1460286 | HC-B 10-KML-H-M1PG16 | | |
| 1460288 | HC-B 10-KML-H-O1M25 | 1412585 | HC-STA-B10-CHWS-1TTM25-ELC-AL |
| 1460289 | HC-B 10-KML-H-O1PG29 | 1412589 | HC-STA-B10-CHWS-1TTP29-ELC-AL |
| 1460290 | HC-B 10-KML-H-O1STM20 | 1412584 | HC-STA-B10-CHWS-1TTM20-ELC-AL |
| 1460291 | HC-B 10-KML-H-O1STM25 | 1412585 | HC-STA-B10-CHWS-1TTM25-ELC-AL |
| 1460292 | HC-B 10-KML-H-O1STM32 | 1412586 | HC-STA-B10-CHWS-1TTM32-ELC-AL |
| 1460316 | HC-B 10-KML-N-O1STM20 | 1412584 | HC-STA-B10-CHWS-1TTM20-ELC-AL |



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

| | | | |
|---------|------------------------|---------|------------------------------------|
| 1460294 | HC-B 10-KMQ-H-M1PG16 | | |
| 1460295 | HC-B 10-KMQ-H-O1M20 | 1412578 | HC-STA-B10-CHWD-1TTM20-ELC-A L |
| 1460296 | HC-B 10-KMQ-H-O1M25 | 1412579 | HC-STA-B10-CHWD-1TTM25-ELC-A L |
| 1460301 | HC-B 10-KMQ-H-O1STM25 | 1412579 | HC-STA-B10-CHWD-1TTM25-ELC-A L |
| 1460042 | HC-B 10-KMQ-N-O1PG16 | 1412581 | HC-STA-B10-CHWD-1TTP16-ELC-A L |
| 1460151 | HC-B 10-KMQ-N-O1STM20 | 1412578 | HC-STA-B10-CHWD-1TTM20-ELC-A L |
| 1584651 | HC-B 10-LB | 1412804 | HC-STA-B10-SL-PLBK |
| 1771406 | HC-B 10-SFQD-52/M1PG16 | | |
| 1771419 | HC-B 10-SFQD-52/M2PG16 | | |
| 1646489 | HC-B 10-SFQD-52/O1M20 | 1412830 | HC-STA-B10-SLFDC-2SSM20-ELC-A L |
| 1646492 | HC-B 10-SFQD-52/O2M20 | 1412830 | HC-STA-B10-SLFDC-2SSM20-ELC-A L |
| 1604748 | HC-B 10-SFQD-52/O2M25 | 1412831 | HC-STA-B10-SLFDC-2SSM25-ELC-A L |
| 1646502 | HC-B 10-SFQD-74/O1M25 | 1412831 | HC-STA-B10-SLFDC-2SSM25-ELC-A L |
| 1771383 | HC-B 10-SML-52/M1PG16 | | |
| 1771396 | HC-B 10-SML-52/M2PG16 | | |
| 1646269 | HC-B 10-SML-52/O1M20 | 1412839 | HC-STA-B10-SLWS-2SSM20-ELC-A L |
| 1604749 | HC-B 10-SML-52/O1M25 | 1412840 | HC-STA-B10-SLWS-2SSM25-ELC-A L |
| 1673449 | HC-B 10-SML-52/O1PG16 | 1412842 | HC-STA-B10-SLWS-2SSP16-ELC-AL |
| 1646272 | HC-B 10-SML-52/O2M20 | 1412839 | HC-STA-B10-SLWS-2SSM20-ELC-A L |
| 1646395 | HC-B 10-SML-74/O1M25 | 1082578 | HC-STA-B10-SHWS-2SSM25-ELC-A L |
| 1646418 | HC-B 10-SML-74/O1M32 | 1082579 | HC-STA-B10-SHWS-2SSM32-ELC-A L |
| 1677636 | HC-B 10-SML-74/O1PG21 | 1082579 | HC-STA-B10-SHWS-2SSM32-ELC-A L |
| 1677649 | HC-B 10-SML-74/O1PG29 | 1082580 | HC-STA-B10-SHWS-2SSM40-ELC-A L |
| 1646285 | HC-B 10-SML-74/O2M25 | 1082578 | HC-STA-B10-SHWS-2SSM25-ELC-A L |
| 1646421 | HC-B 10-SML-74/O2M32 | 1082579 | HC-STA-B10-SHWS-2SSM32-ELC-A L |
| 1586798 | HC-B 10-SMLD-52/M1M20 | | |
| 1771422 | HC-B 10-SMLD-52/M1PG16 | | |
| 1771435 | HC-B 10-SMLD-52/M2PG16 | | |
| 1673465 | HC-B 10-SMLD-52/O1PG16 | 1412846 | HC-STA-B10-SLWSC-2SSP16-ELC- AL |
| 1604750 | HC-B 10-SMLD-52/O2M20 | 1412844 | HC-STA-B10-SLWSC-2SSM20-ELC- AL |
| 1604751 | HC-B 10-SMLD-52/O2M25 | 1412845 | HC-STA-B10-SLWSC-2SSM25-ELC- AL |



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

| | | | |
|---------|------------------------|---------|--------------------------------|
| 1673478 | HC-B 10-SMLD-52/O2PG16 | 1412846 | HC-STA-B10-SLWSC-2SSP16-ELC-AL |
| 1646463 | HC-B 10-SMLD-74/O1M32 | 1082583 | HC-STA-B10-SHWSC-2SSM32-ELC-AL |
| 1646450 | HC-B 10-SMLD-74/O2M25 | 1082582 | HC-STA-B10-SHWSC-2SSM25-ELC-AL |
| 1677681 | HC-B 10-SMLD-74/O1PG29 | 1082585 | HC-STA-B10-SHWSC-2SSM40-ELC-AL |
| 1646476 | HC-B 10-SMLD-74/O2M32 | 1082583 | HC-STA-B10-SHWSC-2SSM32-ELC-AL |
| 1677694 | HC-B 10-SMLD-74/O2PG21 | 1082583 | HC-STA-B10-SHWSC-2SSM32-ELC-AL |
| 1586811 | HC-B 10-SMQ-52/M1M20 | | |
| 1771367 | HC-B 10-SMQ-52/M1PG16 | | |
| 1586824 | HC-B 10-SMQ-52/M2M20 | | |
| 1771370 | HC-B 10-SMQ-52/M2PG16 | | |
| 1604752 | HC-B 10-SMQ-52/O1M20 | 1412835 | HC-STA-B10-SLWD-2SSM20-ELC-AL |
| 1673481 | HC-B 10-SMQ-52/O1PG16 | 1412837 | HC-STA-B10-SLWD-2SSP16-ELC-AL |
| 1604753 | HC-B 10-SMQ-52/O2M20 | 1412835 | HC-STA-B10-SLWD-2SSM20-ELC-AL |
| 1604754 | HC-B 10-SMQ-52/O2M25 | 1412836 | HC-STA-B10-SLWD-2SSM25-ELC-AL |
| 1604755 | HC-B 10-SMQ-74/O1M25 | 1082598 | HC-STA-B10-SHWD-2SSM25-ELC-AL |
| 1604756 | HC-B 10-SMQ-74/O1M32 | 1082599 | HC-STA-B10-SHWD-2SSM32-ELC-AL |
| 1677717 | HC-B 10-SMQ-74/O1PG21 | 1082579 | HC-STA-B10-SHWS-2SSM32-ELC-AL |
| 1604757 | HC-B 10-SMQ-74/O2M25 | 1082598 | HC-STA-B10-SHWD-2SSM25-ELC-AL |
| 1645820 | HC-B 10-SMQ-74/O2M32 | 1082599 | HC-STA-B10-SHWD-2SSM32-ELC-AL |
| 1678444 | HC-B 10-SMQ-74/O2PG29 | 1083164 | HC-STA-B10-SHWD-2SSM40-ELC-AL |
| 1460106 | HC-B 10-TFL-H-M1M25G | | |
| 1460045 | HC-B 10-TFL-H-O1M25G | 1412604 | HC-STA-B10-HHFS-1TTM25-EL-AL |
| 1460046 | HC-B 10-TFL-H-O1M25S | 1412600 | HC-STA-B10-HHFS-1STM25-EL-AL |
| 1460047 | HC-B 10-TFL-H-O1M32G | 1412605 | HC-STA-B10-HHFS-1TTM32-EL-AL |
| 1460048 | HC-B 10-TFL-H-O1PG21G | 1412606 | HC-STA-B10-HHFS-1TTP21-EL-AL |
| 1460049 | HC-B 10-TFL-H-O1PG21S | 1412602 | HC-STA-B10-HHFS-1STP21-EL-AL |
| 1460050 | HC-B 10-TFL-H-O1PG29G | 1412607 | HC-STA-B10-HHFS-1TTP29-EL-AL |
| 1460051 | HC-B 10-TFL-H-O1PG29S | 1412603 | HC-STA-B10-HHFS-1STP29-EL-AL |
| 1460052 | HC-B 10-TFL-H-O1STM20G | 1412629 | HC-STA-B10-HLFS-1TTM20-EL-AL |
| 1460053 | HC-B 10-TFL-H-O1STM20S | 1412624 | HC-STA-B10-HLFS-1STM20-EL-AL |
| 1460054 | HC-B 10-TFL-H-O1STM25G | 1412604 | HC-STA-B10-HHFS-1TTM25-EL-AL |
| 1460055 | HC-B 10-TFL-H-O1STM25S | 1412600 | HC-STA-B10-HHFS-1STM25-EL-AL |
| 1460056 | HC-B 10-TFL-H-O1STM32G | 1412605 | HC-STA-B10-HHFS-1TTM32-EL-AL |
| 1460057 | HC-B 10-TFL-H-O1STM32S | 1412601 | HC-STA-B10-HHFS-1STM32-EL-AL |
| 1460273 | HC-B 10-TFL-N-M1M20S | | |
| 1460033 | HC-B 10-TFL-N-M1PG16G | | |
| 1460038 | HC-B 10-TFL-N-M1PG16S | | |
| 1460070 | HC-B 10-TFL-N-O1M20G | 1412629 | HC-STA-B10-HLFS-1TTM20-EL-AL |



Product Discontinuation

| | | | |
|---------|------------------------|---------|-------------------------------|
| 1460132 | HC-B 10-TFL-N-O1M20S | 1412624 | HC-STA-B10-HLFS-1STM20-EL-AL |
| 1460334 | HC-B 10-TFL-N-O1M25S | 1412625 | HC-STA-B10-HLFS-1STM25-EL-AL |
| 1460036 | HC-B 10-TFL-N-O1PG16G | 1412631 | HC-STA-B10-HLFS-1TTP16-EL-AL |
| 1460041 | HC-B 10-TFL-N-O1PG16S | 1412627 | HC-STA-B10-HLFS-1STP16-EL-AL |
| 1460034 | HC-B 10-TFL-N-O1STM20G | 1412629 | HC-STA-B10-HLFS-1TTM20-EL-AL |
| 1460035 | HC-B 10-TFL-N-O1STM20S | 1412624 | HC-STA-B10-HLFS-1STM20-EL-AL |
| 1460039 | HC-B 10-TFL-N-O1STM25G | 1412630 | HC-STA-B10-HLFS-1TTM25-EL-AL |
| 1460040 | HC-B 10-TFL-N-O1STM25S | 1412625 | HC-STA-B10-HLFS-1STM25-EL-AL |
| 1460071 | HC-B 10-TFQ-H-O1M25G | 1412596 | HC-STA-B10-HHFD-1TTM25-EL-AL |
| 1460072 | HC-B 10-TFQ-H-O1M25S | 1412592 | HC-STA-B10-HHFD-1STM25-EL-AL |
| 1460074 | HC-B 10-TFQ-H-O1PG21G | 1412598 | HC-STA-B10-HHFD-1TTP21-EL-AL |
| 1460075 | HC-B 10-TFQ-H-O1PG21S | 1412594 | HC-STA-B10-HHFD-1STP21-EL-AL |
| 1460076 | HC-B 10-TFQ-H-O1PG29G | 1412599 | HC-STA-B10-HHFD-1TTP29-EL-AL |
| 1460077 | HC-B 10-TFQ-H-O1PG29S | 1412595 | HC-STA-B10-HHFD-1STP29-EL-AL |
| 1460079 | HC-B 10-TFQ-H-O1STM20S | 1412616 | HC-STA-B10-HLFD-1STM20-EL-AL |
| 1460080 | HC-B 10-TFQ-H-O1STM25G | 1412596 | HC-STA-B10-HHFD-1TTM25-EL-AL |
| 1460081 | HC-B 10-TFQ-H-O1STM25S | 1412592 | HC-STA-B10-HHFD-1STM25-EL-AL |
| 1460082 | HC-B 10-TFQ-H-O1STM32G | 1412597 | HC-STA-B10-HHFD-1TTM32-EL-AL |
| 1460083 | HC-B 10-TFQ-H-O1STM32S | 1412593 | HC-STA-B10-HHFD-1STM32-EL-AL |
| 1460060 | HC-B 10-TFQ-N-M1PG16G | | |
| 1460065 | HC-B 10-TFQ-N-M1PG16S | | |
| 1460043 | HC-B 10-TFQ-N-O1M20G | 1412620 | HC-STA-B10-HLFD-1TTM20-EL-AL |
| 1460253 | HC-B 10-TFQ-N-O1M20S | 1412616 | HC-STA-B10-HLFD-1STM20-EL-AL |
| 1460069 | HC-B 10-TFQ-N-O1M25G | 1412621 | HC-STA-B10-HLFD-1TTM25-EL-AL |
| 1460268 | HC-B 10-TFQ-N-O1M25S | 1412617 | HC-STA-B10-HLFD-1STM25-EL-AL |
| 1460063 | HC-B 10-TFQ-N-O1PG16G | 1412622 | HC-STA-B10-HLFD-1TTP16-EL-AL |
| 1460068 | HC-B 10-TFQ-N-O1PG16S | 1412618 | HC-STA-B10-HLFD-1STP16-EL-AL |
| 1460061 | HC-B 10-TFQ-N-O1STM20G | 1412620 | HC-STA-B10-HLFD-1TTM20-EL-AL |
| 1460062 | HC-B 10-TFQ-N-O1STM20S | 1412616 | HC-STA-B10-HLFD-1STM20-EL-AL |
| 1460066 | HC-B 10-TFQ-N-O1STM25G | 1412621 | HC-STA-B10-HLFD-1TTM25-EL-AL |
| 1460067 | HC-B 10-TFQ-N-O1STM25S | 1412617 | HC-STA-B10-HLFD-1STM25-EL-AL |
| 1460096 | HC-B 10-TMQ-H-O1STM20S | 1412633 | HC-STA-B10-HLWD-1STM20-EL-AL |
| 1460097 | HC-B 10-TMQ-H-O1STM25G | 1412612 | HC-STA-B10-HHWD-1TTM25-EL-AL |
| 1460098 | HC-B 10-TMQ-H-O1STM25S | 1412608 | HC-STA-B10-HHWD-1STM25-EL-AL |
| 1460086 | HC-B 10-TMQ-N-M1PG16G | | |
| 1460090 | HC-B 10-TMQ-N-M1PG16S | | |
| 1460091 | HC-B 10-TMQ-N-O1M20S | 1412633 | HC-STA-B10-HLWD-1STM20-EL-AL |
| 1460092 | HC-B 10-TMQ-N-O1M25S | 1412634 | HC-STA-B10-HLWD-1STM25-EL-AL |
| 1460088 | HC-B 10-TMQ-N-O1STM20G | 1412637 | HC-STA-B10-HLWD-1TTM20-EL-AL |
| 1771600 | HC-B 16-AFQD | 1411328 | HC-STA-B16-BFDC-ELC-AL |
| 1771590 | HC-B 16-AML | 1411324 | HC-STA-B16-BWS-ELC-AL |
| 1771613 | HC-B 16-AML D | 1411325 | HC-STA-B16-BWSC-ELC-AL |
| 1771587 | HC-B 16-AMQ | 1411327 | HC-STA-B16-BWD-ELC-AL |
| 1460304 | HC-B 16-KML-H-M1PG21 | | |
| 1460305 | HC-B 16-KML-H-O1M32 | 1412646 | HC-STA-B16-CHWS-1TTM32-ELC-AL |
| 1460306 | HC-B 16-KML-H-O1PG21 | 1412647 | HC-STA-B16-CHWS-1TTP21-ELC-AL |
| 1460307 | HC-B 16-KML-H-O1PG29 | 1412648 | HC-STA-B16-CHWS-1TTP29-ELC-AL |

Product Discontinuation

| | | | |
|---------|------------------------|---------|------------------------------------|
| 1460308 | HC-B 16-KML-H-O1STM25 | 1412645 | HC-STA-B16-CHWS-1TTM25-ELC-A L |
| 1460172 | HC-B 16-KML-H-O1STM32 | 1412646 | HC-STA-B16-CHWS-1TTM32-ELC-A L |
| 1460309 | HC-B 16-KML-H-O1STM40 | | |
| 1460198 | HC-B 16-KML-N-O1PG21 | 1412647 | HC-STA-B16-CHWS-1TTP21-ELC-A L |
| 1460267 | HC-B 16-KML-N-O1STM25 | 1412645 | HC-STA-B16-CHWS-1TTM25-ELC-A L |
| 1460311 | HC-B 16-KMQ-H-M1PG21 | | |
| 1460181 | HC-B 16-KMQ-H-O1M32 | 1412642 | HC-STA-B16-CHWD-1TTM32-ELC-A L |
| 1460313 | HC-B 16-KMQ-H-O1PG21 | 1412643 | HC-STA-B16-CHWD-1TTP21-ELC-A L |
| 1460315 | HC-B 16-KMQ-H-O1STM25 | 1412641 | HC-STA-B16-CHWD-1TTM25-ELC-A L |
| 1460312 | HC-B 16-KMQ-H-O1STM32 | 1412642 | HC-STA-B16-CHWD-1TTM32-ELC-A L |
| 1414349 | HC-B 16-KMQ-H-O1STM40 | | |
| 1460093 | HC-B 16-KMQ-N-O1STM32 | 1412642 | HC-STA-B16-CHWD-1TTM32-ELC-A L |
| 1584664 | HC-B 16-LB | 1412284 | HC-STA-B16-SL-PLBK |
| 1771668 | HC-B 16-SFQD-67/M1PG21 | | |
| 1771671 | HC-B 16-SFQD-67/M2PG21 | | |
| 1604783 | HC-B 16-SFQD-67/O2M25 | 1412849 | HC-STA-B16-SLFDC-2SSM25-ELC-A L |
| 1673685 | HC-B 16-SFQD-67/O2PG21 | 1412853 | HC-STA-B16-SLFDC-2SSP21-ELC-A L |
| 1645655 | HC-B 16-SFQD-84/O1M32 | 1412850 | HC-STA-B16-SLFDC-2SSM32-ELC-A L |
| 1771642 | HC-B 16-SML-67/M1PG21 | | |
| 1771655 | HC-B 16-SML-67/M2PG21 | | |
| 1604784 | HC-B 16-SML-67/O1M25 | 1412861 | HC-STA-B16-SLWS-2SSM25-ELC-A L |
| 1673698 | HC-B 16-SML-67/O1PG21 | 1412863 | HC-STA-B16-SLWS-2SSP21-ELC-AL |
| 1604785 | HC-B 16-SML-67/O2M25 | 1412861 | HC-STA-B16-SLWS-2SSM25-ELC-A L |
| 1646299 | HC-B 16-SML-84/O1M32 | 1082587 | HC-STA-B16-SHWS-2SSM32-ELC-A L |
| 1677869 | HC-B 16-SML-84/O1PG21 | 1082587 | HC-STA-B16-SHWS-2SSM32-ELC-A L |
| 1646308 | HC-B 16-SML-84/O2M32 | 1082587 | HC-STA-B16-SHWS-2SSM32-ELC-A L |
| 1771684 | HC-B 16-SMLD-67/M1PG21 | | |
| 1586882 | HC-B 16-SMLD-67/M2M25 | | |
| 1771697 | HC-B 16-SMLD-67/M2PG21 | | |
| 1604786 | HC-B 16-SMLD-67/O1M25 | 1412865 | HC-STA-B16-SLWSC-2SSM25-ELC- AL |
| 1673711 | HC-B 16-SMLD-67/O1PG21 | 1412867 | HC-STA-B16-SLWSC-2SSP21-ELC- AL |
| 1604787 | HC-B 16-SMLD-67/O2M25 | 1412865 | HC-STA-B16-SLWSC-2SSM25-ELC- AL |

Product Discontinuation

| | | | |
|---------|------------------------|---------|--------------------------------|
| 1673724 | HC-B 16-SMLD-67/O2PG21 | 1412867 | HC-STA-B16-SLWSC-2SSP21-ELC-AL |
| 1645671 | HC-B 16-SMLD-84/O1M32 | 1082590 | HC-STA-B16-SHWSC-2SSM32-ELC-AL |
| 1645697 | HC-B 16-SMLD-84/O1M40 | 1082591 | HC-STA-B16-SHWSC-2SSM40-ELC-AL |
| 1645707 | HC-B 16-SMLD-84/O2M40 | 1082591 | HC-STA-B16-SHWSC-2SSM40-ELC-AL |
| 1677898 | HC-B 16-SMLD-84/O2PG29 | 1082591 | HC-STA-B16-SHWSC-2SSM40-ELC-AL |
| 1771626 | HC-B 16-SMQ-67/M1PG21 | | |
| 1771639 | HC-B 16-SMQ-67/M2PG21 | | |
| 1604788 | HC-B 16-SMQ-67/O1M25 | 1412855 | HC-STA-B16-SLWD-2SSM25-ELC-AL |
| 1604789 | HC-B 16-SMQ-67/O1M32 | 1412856 | HC-STA-B16-SLWD-2SSM32-ELC-AL |
| 1673740 | HC-B 16-SMQ-67/O1PG21 | 1412857 | HC-STA-B16-SLWD-2SSP21-ELC-AL |
| 1604790 | HC-B 16-SMQ-67/O2M25 | 1412855 | HC-STA-B16-SLWD-2SSM25-ELC-AL |
| 1604791 | HC-B 16-SMQ-67/O2M32 | 1412856 | HC-STA-B16-SLWD-2SSM32-ELC-AL |
| 1604792 | HC-B 16-SMQ-84/O1M25 | 1082600 | HC-STA-B16-SHWD-2SSM25-ELC-AL |
| 1604793 | HC-B 16-SMQ-84/O1M32 | 1082601 | HC-STA-B16-SHWD-2SSM32-ELC-AL |
| 1460167 | HC-B 16-SMQ-84/O1PG29 | 1082602 | HC-STA-B16-SHWD-2SSM40-ELC-AL |
| 1604794 | HC-B 16-SMQ-84/O2M32 | 1082601 | HC-STA-B16-SHWD-2SSM32-ELC-AL |
| 1677937 | HC-B 16-SMQ-84/O2PG21 | 1082601 | HC-STA-B16-SHWD-2SSM32-ELC-AL |
| 1460108 | HC-B 16-TFL-H-M1M32G | | |
| 1460110 | HC-B 16-TFL-H-M1PG21G | | |
| 1460111 | HC-B 16-TFL-H-M1PG21S | | |
| 1460112 | HC-B 16-TFL-H-M1PG29G | | |
| 1460113 | HC-B 16-TFL-H-M1PG29S | | |
| 1460114 | HC-B 16-TFL-H-O1M25G | 1412729 | HC-STA-B16-HLFS-1TTM25-EL-AL |
| 1460115 | HC-B 16-TFL-H-O1M25S | 1412725 | HC-STA-B16-HLFS-1STM25-EL-AL |