

<b>PCN Number:</b>	20171107000	<b>PCN Date:</b>	November 14, 2017
<b>Title:</b>	Datasheet for CD4051B, CD4052B, CD4053B		
<b>Customer Contact:</b>	PCN Manager	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



**CD4051B, CD4052B, CD4053B**

SCHS047I – AUGUST 1998 – REVISED SEPTEMBER 2017

Changes from Revision H (April 2015) to Revision I	Page
• Added: ON Channel Leakage Current to the <i>Electrical Characteristics</i> table .....	6
• Added Note 3 to the <i>Electrical Characteristics</i> table .....	6
• Added <a href="#">Figure 13</a> .....	12

The datasheet number will be changing.

Device Family	Change From:	Change To:
CD4051B, CD4052B, CD4053B	SCHS047H	SCHS047I

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/CD4051B>

#### Reason for Change:

To accurately reflect device characteristics.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

#### Changes to product identification resulting from this PCN:

None.

#### Product Affected:

7901502EA	CD4051BNSRE4	CD4052BM96G4	CD4053BM
8101801EA	CD4051BPW	CD4052BMG4	CD4053BM96
CD4051BE	CD4051BPWE4	CD4052BMT	CD4053BM96E4
CD4051BEE3	CD4051BPWG4	CD4052BNSR	CD4053BM96G3
CD4051BEE4	CD4051BPWR	CD4052BNSRG4	CD4053BM96G4
CD4051BF	CD4051BPWRG4	CD4052BPW	CD4053BMG4
CD4051BF3A	CD4052BE	CD4052BPWE4	CD4053BMT
CD4051BM	CD4052BEE4	CD4052BPWR	CD4053BNSR
CD4051BM96	CD4052BF	CD4052BPWRG3	CD4053BPW
CD4051BM96G3	CD4052BF3A	CD4052BPWRG4	CD4053BPWG4
CD4051BM96G4	CD4052BM	CD4053BE	CD4053BPWR

CD4051BMG4	CD4052BM96	CD4053BEE4	CD4053BPWRG3
CD4051BMT	CD4052BM96E4	CD4053BF	CD4053BPWRG4
CD4051BNSR	CD4052BM96G3	CD4053BF3A	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

<b>Location</b>	<b>E-Mail</b>
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>