

<b>PCN Number:</b>	20190424002.0	<b>PCN Date:</b>	April 29, 2019
<b>Title:</b>	Datasheet for TPS2662		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



**TPS2662**

SLVSDT4D – OCTOBER 2017 – REVISED FEBRUARY 2019

Changes from Revision C (July 2018) to Revision D

Page

- Changed SHDN pin voltage from 4 V to 6 V in the *Recommended Operating Conditions* table in the [Specifications](#) section ..... 5

The datasheet number will be changing.

Device Family	Change From:	Change To:
TPS2662	SLVSDT4C	SLVSDT4D

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TPS2662>

#### Reason for Change:

To accurately reflect device characteristics.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

#### Changes to product identification resulting from this PCN:

None.

#### Product Affected:

TPS26620DRCR	TPS26620DRCT	TPS26621DRCR	TPS26621DRCT
TPS26622DRCR	TPS26622DRCT	TPS26623DRCR	TPS26623DRCT
TPS26624DRCR	TPS26624DRCT	TPS26625DRCR	TPS26625DRCT

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
WW PCN Team	<a href="mailto:PCN_ww_admin_team@list.ti.com">PCN_ww_admin_team@list.ti.com</a>