



November 18, 2014

Product Discontinuation Notification

ICCNexergy has decided to discontinue a select number of Elpac brand power supplies (see Exhibit A). These product discontinuations are a result of newly developed models that are direct replacements for older units or market decline on legacy products. Recommended replacements have been provided where possible. We urge you to review specifications with your end customers to determine the suitability of the replacement product for their application. Datasheets can be found at www.iccnexergy.com.

For the FW series of products, please refer customers to the newer FWA20, FWE30 and FWE50 series of products for replacements. See links to datasheets below:

<http://www.iccnexergy.com/elpac/ite-power-supplies/external/fwa020-class-i/>

<http://www.iccnexergy.com/elpac/ite-power-supplies/external/fwe030-class-i/>

<http://www.iccnexergy.com/elpac/ite-power-supplies/external/fwe050-class-i/>

The FWC18, FWC30 and FWC50 series will remain an active series for now with discontinuation being announced sometime during the second half of 2015. For any customer(s) currently using the FW series, we recommend offering them the newer FWA or FWE series of products as listed above.

In order to minimize product flow disruption, we will honor all existing open orders for the discontinued units and a last time purchase for these items can be placed. Purchase orders for last time buys must be received no later than January 30, 2015 and product(s) must ship before June 30, 2015.

We apologize for the inconvenience this decision may cause and will be happy to address any questions or concerns.

Sincerely

Steve Noble
ICCNexergy, Inc.
Distribution Sales Manager

4 Westbrook Corporate Center Suite 900 | Westchester, IL 60154
Phone: 708-836-3800 | Fax: 708-836-3801

China *Germany* *USA* *Mexico* *Hong Kong* *United Kingdom*

EXHIBIT A
Discontinued Product List – Effective January 30, 2015

Discontinued Part Number	Suggested Replacement
FTA040009A	No replacement
FTA040012A	No replacement
FTA040015A	No replacement
FTA040024A	No replacement
FTB080009A	No replacement
FTB080012A	No replacement
FTB080015A	No replacement
FTB080024A	No replacement
FVA100012A	No replacement
FVA100015A	No replacement
FVA100018A	No replacement
FVA100024A	No replacement
FW1805-760F	FWA020005A-10B
FW1812-760F	FWA020012A-10B
FW1818-760F	No replacement
FW1824-760F	FWA020024A-10B
FW3012-760F	FWE030012A-10B
FW3015-760F	FWE030015A-10B
FW3018-760F	FWE030018A-10B
FW3024-760F	FWE030024A-10B
FW5012-760F	FWE050012A-10B
FW5018-760F	FWE050018A-10B
FW5024-760F	FWE050024A-10B
FWB100012A-12B	FWC100012A-12B
FWB100015A-11B	FWC100015A-11B
FWB100018A-11B	FWC100018A-11B
FWB100024A-11B	FWC100024A-11B
MS4009F	No replacement

Discontinued Part Number	Suggested Replacement
MS4012F	No replacement
MS4015F	No replacement
MS4018F	No replacement
MS4024F	No replacement
MS6509F	No replacement
MS6512F	No replacement
MS6515F	No replacement
MS6524F	No replacement
MSM0705	No replacement
MSM0712	No replacement
MSM0715	No replacement
MSM0724	No replacement
MSM0728	No replacement
MSM2012	No replacement
MSM2015	No replacement
MSM2024	No replacement
MSM7524	No replacement
MSMP15012F	No replacement
MSMP15015F	No replacement
MSMP15024F	No replacement
MSMP15028F	No replacement
MSMP15048F	No replacement
MSMP25012F	FXA350012A
MSMP25015F	FXA350015A
MSMP25024F	FXA350024A
MSMP25028F	FXA350028F
MSMP25048F	FXA350048F

4 Westbrook Corporate Center Suite 900 | Westchester, IL 60154
 Phone: 708-836-3800 | Fax: 708-836-3801