

## **PRODUCT DISCONTINUANCE NOTICE (PDN)**

PDN Number: <u>14-0009</u> Issue Date: April 11, 2014 Product(s) Affected: See Table Below Last Purchase Date: October 11, 2014 Last Shipment Date: January 11, 2015	Reason for Discontinuing Listed Products:   Obsolete Design/Process Technology   Obsolete Package/Assembly   Technology   No current or rapidly declining sales   Other:   See Product List Attachment:   Yes;   No
Pericom Contact: <u>Raul Aman</u> Title: <u>Quality Assurance Director</u> Phone: <u>408-232-9100</u> Fax: <u>408-434-1040</u> eMail: <u>PCN_PDN@pericom.com</u>	* Note: Pericom would like to notify all customers that products listed below have been phased- out due to rapidly declining sales. In some cases, availability may be limited, and the normal last time purchase and shipment methods may not be supported. Customers are encouraged to provide requirements as early as possible. Pericom apologizes for any inconvenience this situation may cause.

Product Line	Product Family	Part Number	Description	PkgLds	Comments for Customers
Clock	PI49FCT807CTSE	Clock Buffer	10-Output Non-Inverting Clock	\$20	No Replacement
Clock	PI49FCT807CTSEX	Clock Buffer	10-Output Non-Inverting Clock	S20	No Replacement
Clock	PI49FCT807TQE	Clock Buffer	10-Output Non-Inverting Clock	Q20	No Replacement
Clock	PI49FCT807TQEX	Clock Buffer	10-Output Non-Inverting Clock	Q20	No Replacement
Switch	PI5A121TEX	Analog Switch	Single SPST, NO A/SW	T05	contact jbai@pericom.com
Switch	PI5C3301TEX	Bus Switch	Dual Bus Switch	T05	contact jbai@pericom.com



Customer Acknowledgement:								
Customer:								
Name:	••••							
Title:								
Date:								
E-Mail:								
Phone:								
Fax:	Fax:							
Customers may use this form to acknowledge receipt of this notification, or can e-mail the Pericom contact noted above.								
Customer Comments:								
Pericom Internal Use Only:								
Location:	S PSC	🗌 PTI	DPSE-TW	PSE-SD				
PSETW PDN: N/A								