

PRODUCT CHANGE NOTIFICATION

TO: ALL AFFECTED CUSTOMERS

FROM: QUALTEK ELECTRONICS

DATE: September 16, 2020

CLASSIFICATION OF CHANGE: FAD1-06020 SERIES REMOVAL OF SLEEVE BEARING

THE FOLLOWING PART NUMBERS ARE OBSOLETE:

PART NUMBER	RECOMMENDED PART NUMBER REPLACEMENT
FAD1-06020BSAW11	FAD1-06020BHAW11
FAD1-06020BSLW11	FAD1-06020BHLW11
FAD1-06020BSMW11	FAD1-06020BHMW11
FAD1-06020BSHW11	FAD1-06020BHHW11
FAD1-06020CSAW11	FAD1-06020CHAW11
FAD1-06020CSLW11	FAD1-06020CHLW11
FAD1-06020CSMW11	FAD1-06020CHMW11
FAD1-06020CSHW11	FAD1-06020CHHW11
FAD1-06020CSJW11	FAD1-06020CHJW11
FAD1-06020CSKW11	FAD1-06020CHKW11
FAD1-06020DSMW11	FAD1-06020DHMW11
FAD1-06020DSHW11	FAD1-06020DHHW11

THE RECOMMENDED REPLACEMENTS UTILIZE OUR HYDRO DYNAMIC BEARING INSTEAD OF SLEEVE BEARING. THIS BEARING STRUCTURE PROVIDES A LONGER LIFE 50K HOURS VS 30K HOURS WHILE ALSO PROVIDING SIMILAR LEVELS OF NOISE AND PERFORMANCE.

LAST TIME BUY: NONE.

CONTACT INFORMATION: PLEASE CONTACT QUALTEK ELECTRONICS CUSTOMER SERVICE FOR AVAILABILITY.

PHONE: 440-951-3300

FAX: 440-951-7252