

<b>PDN Number:</b>	20160729001	<b>PDN Date:</b>	8/04/2016
<b>Title:</b>	Discontinuance of Select Devices sourced in Dongbu foundry		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Last date to order:</b>	2/04/2017	<b>Last date to ship:</b>	2/04/2018
<b>Change Type:</b>	Product Discontinuance - End Of Life		
<b>Product Discontinuance Notification Details</b>			
<b>Description of Discontinuance:</b>			
<p>Texas Instruments, Incorporated (TI) is announcing the discontinuance of select devices sourced in the Dongbu foundry. A life time buy is being offered per the date show above. Recommended replacements are also offered on some devices as shown in the Product Affected Section.</p> <p>NOTE: There are no samples offered for withdrawn/obsolete products. For samples of any replacement products, please contact your local sales representative.</p>			
<b>Reason for Withdrawal/Discontinuance:</b>			
Dongbu is discontinuing technologies used to make these devices			
<b>Product Affected:</b>			
Product Being Discontinued	RECOMMENED REPLACEMENT PRODUCTS	REPLACEMENT CODES	
CDCV857DGG	CDCV857BDGG	Q	
CDCV857DGGG4	CDCV857BDGG	Q	
CDCV857DGGGR	CDCV857BDGGGR	Q	
CDCV857DGGGRG4	CDCV857BDGGGR	Q	
SLK2511CPZP	None	Not Applicable	
SLK2511IPZP	None	Not Applicable	
SLK2721IPZP	None	Not Applicable	
SN65LV1021DB	DS92LV1021AMSA	Q	
SN65LV1021DBG4	DS92LV1021AMSA	Q	
SN65LV1021DBR	DS92LV1021AMSA	Q	
SN65LV1021DBRG4	DS92LV1021AMSA	Q	
SN65LV1023ADB	SN65LVDS93DGG	F	
SN65LV1023ADBG4	SN65LVDS93DGG	F	
SN65LV1023ADBR	SN65LVDS93DGG	F	
SN65LV1023ARHBR	SN65LVDS93DGG	F	
SN65LV1023ARHBT	SN65LVDS93DGG	F	
SN65LV1023DB	SN65LVDS93DGG	F	
SN65LV1224BDB	DS92LV1224TMSA	Q	
SN65LV1224BDBG4	DS92LV1224TMSA	Q	
SN65LV1224BDBR	DS92LV1224TMSA	Q	
SN65LV1224BDBRG4	DS92LV1224TMSA	Q	
SN65LV1224BRHBR	DS92LV1224TMSA	Q	
SN65LV1224BRHBRG4	DS92LV1224TMSA	Q	

SN65LV1224BRHBT	DS92LV1224TMSA	Q
SN65LV1224BRHBTG4	DS92LV1224TMSA	Q
TAS5001PFB	TAS5086/TAS5558	F
TAS5001PFBR	TAS5086/TAS5558	F
TAS5001PFBG4	TAS5086/TAS5558	F
TAS5010PFB	TAS5086/TAS5558	F
TAS5010PFBG4	TAS5086/TAS5558	F
TAS5010PFBR	TAS5086/TAS5558	F
TAS5010PFBR	TAS5086/TAS5558	F
TAS5012PFB	TAS5086/TAS5558	F
TAS5012PFB	TAS5086/TAS5558	F
TAS5012PFBG4	TAS5086/TAS5558	F
TAS5012PFBR	TAS5086/TAS5558	F
TAS5012PFBR	TAS5086/TAS5558	F
TAS5076PFC	TAS5086/TAS5558	F
TAS5076PFCG4	TAS5086/TAS5558	F
TAS5725RGZR	None	Not Applicable
TAS5725RGZT	None	Not Applicable
TL16C752BPT	TL16C752DPFBR	P
TL16C752BPTR	TL16C752DPFBR	P
TLC320AD77CDB	TLV320AIC3104IRHBT	F
TLC320AD77CDBG4	TLV320AIC3104IRHBT	F
TLC320AD77CDBR	TLV320AIC3104IRHBR	F
TLK1201AIRCP	TLK2201BIRCP	F
TLK1201AIRCPG4	TLK2201BIRCP	F
TLK1201AIRCPR	TLK2201BIRCPR	F
TLK1201AIRCPRG4	TLK2201BIRCPR	F
TLK1201ARCP	TLK2201BRCP	F
TLK1201ARCPG4	TLK2201BRCP	F
TLK1201ARCPR	TLK2201BRCPR	F
TLK1201ARCPRG4	TLK2201BRCPR	F
TLK1201IRCP	TLK2201BIRCP	F
TLK1201IRCPR	TLK2201BIRCPR	F
TLK1201RCP	TLK2201BRCP	F
TLK1211RCP	TLK2201BIRCP	F
TLK1211RCPG4	TLK2201BIRCP	F
TLK1221RHAR	TLK2201BIRCP	F
TLK1221RHARG4	TLK2201BIRCP	F
TLK1221RHAT	TLK2201BIRCP	F
TLK1221RHATG4	TLK2201BIRCP	F
TLK1521IPAP	TLK1501IRCP	F
TLK1521IPAPG4	TLK1501IRCP	F
TLK2201AJRGQE	TLK2201BIRCP	F
TLK2201AJRZQE	TLK2201BIRCP	F
TLK2201IRCP	TLK2201BIRCP	F

TLK2201JRGQE	TLK2201BIRCP	F
TLK2201RCP	TLK2201BIRCP	F
TLK2201RCPR	TLK2201BIRCPR	F
TLK2211RCP	TLK2201BIRCP	F
TLK2211RCPR	TLK2201BIRCP	F
TLK2211RCPRG4	TLK2201BIRCP	F
TLK2218ZPV	TLK2226ZEA	F
TLK2521IPAP	TLK2501IRCP	F
TLK2521IPAPG4	TLK2501IRCP	F
TLK2541PFP	TLK2501IRCP	F
TLK2541PFPG4	TLK2501IRCP	F
TLK2541PFPR	TLK2501IRCP	F
TLK2541PFPRG4	TLK2501IRCP	F
TLK2701IRCP	TLK2501IRCP	F
TLK2701IRCPG4	TLK2501IRCP	F
TLK2701IRCPR	TLK2501IRCPR	F
TLK2701IRCPRG4	TLK2501IRCPR	F
TLK2711AIRCP	TLK2501IRCP	F
TLK2711AIRCPR	TLK2501IRCP	F
TLK2711IRCP	TLK2501IRCP	F
TLK2711IRCPG4	TLK2501IRCP	F
TLK3101IRCP	TLK2501IRCP	F
TLK3101IRCPG4	TLK2501IRCP	F
TLK3114SCGPV	TLK1003AAJ	F
TLK4015IGPV	TLK1501IRCPR	F
TLK4015IZPV	TLK1501IRCPR	F
TLK4120IZPV	TLK3134ZEL	F
TLV320AIC3006IZQER	None	Not Applicable
TLV320AIC37IZQER	None	Not Applicable
TLV320DAC33BNIZQCR	None	Not Applicable
TLV320DAC33BNIZQCT	None	Not Applicable
TLV320DAC33NIZQCR	None	Not Applicable
TUSB5052PZ	TUSB3410VF	F
TWL93017EZPHR	None	Not Applicable

**Replacement Notes:**

F = Similar functionality but not equivalent.

P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.

S = EXACT equivalent in functionality and parametrically to the compared device.

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

<b>Location</b>	<b>E-Mail</b>
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>